SRFELINK EPIRB Recall and Replacement Program

Orolia Limited, owners of Kannad Marine have become aware of an issue affecting Kannad SAFELINK EPIRBs which could result in the beacon not operating in an emergency situation.



Part No's Affected	Description	Date Range
K1202311	EPIRB SAFELINK Manual+ GPS	All
K1202367	EPIRB SAFELINK Auto GPS	All

If you suspect that you may have an affected beacon (only Safelink EPIRB auto and manual), you should:

- Not use the SAFELINK as the primary Search and Rescue beacon on board your vessel
- Visit <u>www.safelinkepirbsupport.co.uk</u> for full details and instructions for return and replacement



www.safelinkepirbsupport.co.uk